

N1019F

Date: 06/17/2026

Tach Time: 5697.5

HobbsTime: 8131.4

TT: 15550.5



Airframe

Performed 100 hour and Annual inspection IAW FAR 43 appendix D.

C/W AD 76-07-12 - Ignition Switch Op Check. OK. Next Due Tach Time 5797.5

C/W AD 2011-10-09 - Seat Track and Rollers. Next Due 06/30/2027 Tach Time 5797.5

C/W AD 2001-32-03 - Map Light Wiring. OK. Next Due 06/30/2027

C/W 91.207(d) ELT Battery Inspection and Operational Check. Next Due 06/30/2027.

ELT Battery due 07/2027.

Replace L/H fuel tank vent line with McFarlane p/n MC0523559-12K

All AD's current and C/W as of 06/17/2026

I hereby certify that this Airframe was inspected in accordance with a 100 hour and Annual Inspection in the scope and detail of 14 CFR Part 43, Appendix D, is determined to be in an airworthy condition as of the date of this logbook service record, and is approved for return to service.

Thomas A Deason 3082509 I&A

A handwritten signature in black ink, appearing to read "Thomas A Deason", is written over the printed name and number.